


SECTION A-A



NOTES

1. MACHINE TO DRAWING DIMENSIONS AND CAD DATA MODEL.
2. BREAK ALL SHARP CORNERS
3. INSPECT TO DRAWING DIMENSIONS AND CAD DATA MODEL.
4. PART MARK PART NUMBER WHERE INDICATED 'XXXX'
5. BAG WITH ANTI CORROSIVE PROTECTION PRIOR TO DELIVERY.
6. ANY QUERIES/DEVIATIONS PLEASE REPORT TO SMALL SPARK D.O

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN MILLIMETERS		FINISH:		DEBURR AND BREAK SHARP EDGES		DO NOT SCALE DRAWING		REVISION 00	
SURFACE FINISH:									
TOLERANCES:									
LINEAR:									
ANGULAR:									
DRAWN		NAME		SIGNATURE		DATE		TITLE:	
MIKE RILEY						09/12/22		GRAIN CHAMBER	
CHK'D									
APPV'D									
MFG									
Q.A									
						MATERIAL:		DWG NO.	
						STAINLESS STEEL 316		00004-NA2-00	
						WEIGHT:		SCALE:1:2	
								SHEET 1 OF 1	
								A3	